

INSPECTION SCHEDULE

3/21/2023 SCHEDULE

| PERMIT # | # | STREET ADDRESS | INSPECTION | INSPECTOR |
|----------|-------|-----------------------|-------------|-----------|
| 20000101 | 1009 | Ranch Road 620 N | CT | DARREN |
| 22000819 | 133 | Serene Hilltop Circle | BWP | DARREN |
| 22000820 | 213 | Baldovino Skwvay | BWP | DARREN |
| 22000820 | 213 | Baldovino Skwvay | EX | DARREN |
| 22000836 | 209 | Baldovino Skwvay | BWP | DARREN |
| 21000292 | 618 | Buena Onda Wav | FE,FM,FB,CP | GERALD |
| 21000975 | 710 | Rawson bend | FE,FM,FB,CP | GERALD |
| 21001225 | 414 | Cartwheel Bend | FE,FM,FB,CP | GERALD |
| 21001230 | 608 | Bonfisk bend | FE,FB | GERALD |
| 21001266 | 901 | Echelon place | FE,FM,FB,CP | GERALD |
| 21001269 | 800 | Lauren Bell | FE,FM,FB,CP | GERALD |
| 21001737 | 911 | Bristol Creek Bend | FE,FM,FB,CP | GERALD |
| 21001832 | 412 | Sitlington | FE,FM,FB,CP | GERALD |
| 21000167 | 235 | Canvon turn trail | FR,MR,ER | I/O |
| 22000222 | 205 | Olivia Drive | FR,MR,FR,IN | I/O |
| 22000552 | 617 | Buena onda way | VT,SL | I/O |
| 22001206 | 213 | Tellus | EX | I/O |
| 22001624 | 502 | Primo Fiore Terrace | PS | I/O |
| 23000666 | 101 | blackwolf run | PS | I/O |
| 22000120 | 603 | Buena Onda | SL | RANDY |
| 22000241 | 507 | Elworth | FW | RANDY |
| 22000249 | 603 | Gunison Drive | IN | RANDY |
| 22000334 | 482 | Primo Fiore Terrace | WB | RANDY |
| 22000382 | 808 | Arundel Rd | FW | RANDY |
| 22000408 | 912 | Arundel road | SL | RANDY |
| 22000874 | 301 | Cartwheel Bend | IN | RANDY |
| 18001991 | 2909 | Flintrock Trace | ER | STEPHEN |
| 18001991 | 2909 | Flint Rock Trace | VT,SL | STEPHEN |
| 20000754 | 15085 | Dorothy | EX | STEPHEN |
| 21001047 | 804 | Lauren Belle | FB | STEPHEN |
| 22000488 | 1008 | Ranch Road 620 S | HV | STEPHEN |

3/20/2023 RESULTS

| PERMIT # | # | STREET ADDRESS | INSPECTION | RESULTS |
|----------|-------|----------------------|-------------|---------|
| 21000284 | 313 | Aguaia Court | FE,FM,FB,CP | PASS |
| 21001799 | 105 | Brooks Hollow Rd | PD | PARTIAL |
| 22000067 | 903 | Bristol | FE,FM,FB,CP | PASS |
| 22000563 | 112 | Burgess Cove | PD | PASS |
| 22001624 | 502 | Primo Fiore Terrace | PS | CANCEL |
| 17001930 | 1002 | Barrie | IN | PARTIAL |
| 21001971 | 15228 | Dave Drive | LO | PASS |
| 22001490 | 129 | Lakota Pass | LO | PASS |
| 22000071 | 6 | Lakeway centre court | FN,ER | PASS |
| 22000626 | 15302 | Barrie Drive | FR,MR,ER | FAIL |
| 22000686 | 900 | Bristol Creek Bend | EX | PASS |
| 22000739 | 306 | Wester Ross Lane | FN | PASS |
| 22001334 | 123 | Lakeway Dr | FN,FR | PASS |

BUILDING:
 LO = LAYOUT
 FN = FOUNDATION/FOOTING
 EX = SHEATHING
 WP = WATERPROOFING
 FR = FRAME
 MR = MECHANICAL ROUGH
 ER = ELECTRICAL ROUGH
 IN = INSULATION
 VT = MASONRY VENEER TIE
 SL = STUCCO LATH
 FW = FLATWORK/DRIVEWAY
 WB = DRY WALL / TILE BACKER (Wallboard)
 FE = FINAL ELECTRICAL
 FM = FINAL MECHANICAL
 FB = FINAL BUILDING
 CP = COMPLIANCE

POOL:
 PL = POOL LAYOUT
 PS = POOL SHELL/BONDING (Pre-Gunite)
 PD = POOL DECK/BONDING
 PB = POOL BARRIER
 PF = POOL FINAL

ALTERATIONS:
 HV = HVAC
 RR = REROOF
 SO = SOLAR

OTHER:
 CT = COURTESY
 STR = SHORT TERM RENTAL (COMPLIANCE)

#